Inspection Snapshot

Inspection ID:

539604

Inspection Time: Inspection End

10:18 AM - 04:43 PM

Inspection Start

Date:

07/07/2015

Date:

07/08/2015

Property ID:

TX005000002

Property Type:

Public Housing

Property Name:

Allen Parkway Village

Inspection State:

Successful

Score:

98b*

Property Profile

Property Name:

Allen Parkway Village

Scattered Site?

No

Multiple Site?

No

Address Line 1:

1600 ALLEN PARKWAY

Address Line 2:

City:

HOUSTON

State:

TX

ZIP:

Fax:

77019

Extension:

IX

Phone:

(713) 651-1250

(713) 651-1255

Extension: Email:

tkazia@housingforhouston.com

	, ,					
	Building			Units		
Type	Expected	Actual	Sampled	Expected	Actual	Sampled
Residential	40	40	25	278	278	25
Common	0	2	2	_	_	-
Total	40	42	27	278	278	25

Occupancy Information					
No. of Occupied Units	Occupancy Rate	Inspect Vacant Units			
278	100%	No			

1403 BLUEBONNET PL,1501 BLUEBONNET,1409 BLUEBONNET,1609 BLUEBONNET,1407 BP,2109 BP,1405 BP,2001 BP,2101 BP,2025 BP,2101 BP,810 CROSBY,605 PARK Comments TRAILVISTA,818 PTV,722 PTV,720 PTV,807 PTV PTV,1412 BAYOU OAKS VISTA,1316 BOV7

Report generation date/time: 07/08/2015 07:21 PM

Score Version: 1

Page: 2 of 43

Participant Profile

Executive Director [Primary Contact / Not Present During Inspection]

Name (F, MI, L):

Tory Gunsolley

Organization:

HOUSTON HOUSING AUTHORITY

Address Line 1:

2640 Fountain View Drive

Address Line 2:

Suite 400

City:

Houston

State:

TX

ZIP:

77057

Extension:

Phone:

(713) 260-0522

Extension:

Fax:

(713) 260-0822

Email:

tgunsolley@housingforhouston.com

Management Agent [Present During Inspection]

Name (F, MI, L):

TAYYAB KAZIA

Organization:

HOUSTON HOUSING AUTHORITY

Address Line 1:

2640 FOUNTAIN VIEW DR

Address Line 2:

City:

HOUSTON

State:

TX

ZIP:

77057

Extension:

Phone:

(713) 260-0755

Extension:

Fax:

(713) 260-0822

Email:

tkazia@housingforhouston.com

Site Manager [Present During Inspection]

Name (F, MI, L):

PAULA ROBERSON

1600 ALLEN PARKWAY

Organization:

HOUSTON HOUSING AUTHORITY

Address Line 1:

Address Line 2:

Citv:

HOUSTON

State:

TX

ZIP:

77019

Extension:

Phone:

(713) 651-1250

Extension:

Fax:

(713) 651-1255

Email:

proberson@housingforhouston.com

Score Summary

Area	Possible Points	Deductions(Excluding H&S)	Pre H&S Points	H&S Deductions	Final Points
Site	18.76	0.00	18.76	0.00	18.76
Building Exterior	16.72	0.19	16.53	0.00	16.53
Building Systems	17.23	0.00	17.23	0.00	17.23
Common Area	0.34	0.00	0.34	0.00	0.34
Unit	46.95	0.84	46.12	0.77	45.35
Total	100.00	1.02	98.98	0.77	98.21

Score Version: 1

Score Date: 07/08/2015

Final Score: 98b*

Health & Safety Summary

	Site	Buildings	Units	Total			
Non-Life Threatening (NLT)							
Actual	0	0	3	3			
Projected	0	0	33	33			
Life Threateni	Life Threatening (LT)						
Actual	0	0	0	0			
Projected	0	0	0	0			
Smoke Detectors (SD)							
Actual	0	0	1	1			
Projected	0	0	11	11			
Overall							
Actual	0	0	4	4			
Projected	0	0	44	44			

Health and Safety Narrative

1 site, 27 buildings and 25 units were inspected.

4 health and safety deficiencies(HSD) were observed.

Percentage Inspected:

Site (PIS): 100% Building (PIB): 64% Unit (PIU): 9%

Projected HSD:

Site = (Actual HSDS) / PIS Building = (Actual HSDB) / PIB Unit = (Actual HSDU) / PIU

If all buildings and units were inspected, it is projected that a total of 44 health and safety deficiencies would apply to the property.

Systemic Deficiencies

Type	Area	ltem	Deficiency	B/U with defects		%
Ordinary	BE	FHEO - Accessibility to	BE- Obstructed or Missing Accessibility	18	27	67
distribution		Main Floor Entrance	Route (FHEO Accessibility to Main			
***			Floor Entrance)			

Note:

B/U - Indicates Buildings or Units

BE - Indicates Building Exterior

BS - Indicates Building Systems

CA - Indicates Common Areas

Capital items are repairs that generally require large cash outlays. (Items such as new roofs and new appliances)

Ordinary items are repairs that require smaller cash outlays. (Items such as light fixtures, fire extinguishers and smoke detectors)